			Above			
			Ceiling	Mudded		
		Floor Tiles	Fire	Pipe	Ceiling	Pipe
Item #	Building	(& mastic)	Proofing	<b>Fittings</b>	Tiles	Insulation

1 106. Filmore House

Mechanical Rooms	Gasket Material	Window Caulking Glazing	Transite	Dry Wall Compound	Crawl Space	Fire Doors

or structures for which original construction commenced on or surveys on any proposed demolition or renovation.