

Item #	Building	Floor Tiles (& mastic)	Above Ceiling Fire Proofing	Mudded Pipe Fittings	Ceiling Tiles	Pipe Insulation
1	11. O'Connor Hall - Constructed 1958					
2	Basement	Abated	No	Abated	No	Abated
3	Ground Floor	Abated	No	Abated	No	Abated
4	First Floor	Abated	No	Abated	No	Abated
5	Second Floor	Abated	No	Abated	No	Abated
6	Third Floor	Abated	No	Abated	No	Abated

Mechanical Rooms	Gasket Material	Window Caulking Glazing	Transite	Dry Wall Compound	Crawl Space	Fire Doors
Abated	Abated	Abated	No	Abated	Abated	Abated
N/A	N/A	Abated	No	Abated	N/A	Abated
N/A	N/A	Abated	No	Abated	N/A	Abated
N/A	N/A	Abated	No	Abated	N/A	Abated
N/A	N/A	Abated	No	Abated	N/A	Abated