

Item #	Building	Floor Tiles (& mastic)	Above Ceiling Fire Proofing	Mudded Pipe Fittings	Ceiling Tiles	Pipe Insulation
--------	----------	---------------------------	--------------------------------------	----------------------------	------------------	--------------------

7	12. Johnson Hall -	Constructed	1959			
---	--------------------	-------------	------	--	--	--

8

Mechanical Rooms	Gasket Material	Window Caulking Glazing	Transite	Dry Wall Compound	Crawl Space	Fire Doors
N/A	N/A	Abated	No	Abated	Abated	Abated
N/A	N/A	Abated	No	Abated	N/A	Abated
N/A	N/A	Abated	No	Abated	N/A	Abated
N/A	N/A	Abated	No	Abated	N/A	Abated