

| Item # | Building | Floor Tiles (& mastic) | Above Ceiling Fire Proofing | Mudded Pipe Fittings | Ceiling Tiles | Pipe Insulation |
|--------|------------------|---------------------------|--------------------------------------|----------------------------|------------------|--------------------|
| | | | | | | |
| 1 | 140. Hunter Hall | | | | | |
| | | | | | | |

NYS Code Rule 56 does not require a building survey for buildings after January 1, 1974. However, we perform asbestos :

| Mechanical Rooms | Gasket Material | Window Caulking Glazing | Transite | Dry Wall Compound | Crawl Space | Fire Doors |
|------------------|-----------------|-------------------------|----------|-------------------|-------------|------------|
| | | | | | | |
| | | | | | | |
| | | | | | | |

or structures for which original construction commenced on or surveys on any proposed demolition or renovation.