

Item #	Building	Floor Tiles (& mastic)	Above Ceiling Fire Proofing	Mudded Pipe Fittings	Ceiling Tiles	Pipe Insulation
2	42. Cayuga - Constructed 1972					
3	First Floor	Yes	No	PACM	No	PACM
4	Second Floor	Yes	No	PACM	No	PACM
5	Third Floor	Abated	No	PACM	Abated	PACM
6	Fourth Floor	Abated	No	PACM	Abated	PACM
7	Fifth Floor	Abated	No	PACM	Abated	PACM

Mechanical Rooms	Gasket Material	Window Caulking	Transite	Dry Wall Compound	Crawl Space	Fire Doors
Abated	PACM	N/A	N/A	PACM	N/A	Yes
N/A	PACM	N/A	N/A	PACM	N/A	Yes
N/A	PACM	N/A	N/A	PACM	N/A	Yes
N/A	PACM	N/A	N/A	PACM	N/A	Yes
N/A	PACM	N/A	N/A	PACM	N/A	Yes