

Item #	Building	Floor Tiles (& mastic)	Above Ceiling Fire Proofing	Mudded Pipe Fittings	Ceiling Tiles	Pipe Insulation
1	50. Brandywine Hall - Constructed 1984					

NYS Code Rule 56 does not require a building survey for buildings after January 1, 1974. However, we perform asbestos :

Mechanical Rooms	Gasket Material	Window Caulking Glazing	Transite	Dry Wall Compound	Crawl Space
-----------------------------	----------------------------	--	-----------------	------------------------------	------------------------

